RiteStart Home Inspections Home Inspection Report



1234 Main St, Orlando, FL 34711 Inspection prepared for: Sample Inspection Real Estate Agent: -

Date of Inspection: 7/23/2016 Time: 8:00 AM Age of Home: 1993 Size: 2702 Weather: Sunny Order ID: 77

Inspector: Luis Martinez License # HI8569 1970 E Osceola Pkwy #151, Kissimmee, FL 34743 Phone: (321) 209-5939 Email: Imartinez@ritestarthomeinspections.com



NOTICE TO THIRD PARTIES: This Report is the exclusive property of RiteStart Home Inspections and the Client(s) listed above and is not transferable to any third parties or subsequent buyers. Our inspection and this Report have been performed with a written contract agreement that limits its scope and usefulness. Unauthorized recipients are therefore advised not to rely upon this Report, but rather to retain the services of an appropriately qualified home inspector of their choice to provide them with their own inspection and report.

Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done for your records.

• Some of the exterior outlets had no Ground Fault Circuit Interrupter (GFCI) protection of home electrical outlets was provided in the home at the time of inspection. Although GFCI

Grounds
Page 5 Item: 5 GFCI

		protection may not have been required at the time the home was built, for safety reasons, consider upgrading the electrical system to include GFCI protection at the following locations: Bathrooms, Outside, Garages, Kitchens, Laundry rooms and Within 6 feet of all plumbing fixtures
Page 5 Item: 7	Exterior Faucet Condition	• Hose bib handle is coming off of structure. Recommend securing to prevent moisture intrusion into home and also damage to pipe.
Page 7 Item: 11	Sprinklers	• A few of the sprinkler heads are spraying structure and main electrical panel. We recommend adjusting the heads so they do not spray the house and prevent it from further staining siding.
Pool	-	
Page 11 Item: 18	Remote	• Check system warning observed on remote. Recommend speaking to owner on functioning parts of pool system and or contacting a licensed pool technician to learn how to run the pool system.
Exterior Areas		
Page 12 Item: 4	Siding Condition	• Some wood deterioration noted. Have repaired as necessary. Staining also observed due to sprinkler system spraying structure. Recommend adjusting sprinkler to move heads away as it is adding to the early deterioration of siding.
Roof		
Page 13 Item: 2	Roof Condition	• At the time of the inspection, asphalt composition shingles covering the roof of this home appeared to be near the end of their useful lives. The Inspector recommends that before the expiration of your Inspection Objection Deadline, you consult with a qualified roofing contractor to discuss options and costs for replacement.
Page 13 Item: 4	Gutter	• The gutters had moderate general corrosion visible. Continued corrosion will eventually result in leaking gutters. Good maintenance practices will help extend the long-term service life of the gutters.
Page 14 Item: 7	Chimney	• Minor mortar deterioration at chimney;rust over the cap. Recommend cleaning and maintenance as needed to prevent further deterioration.
Attic		

Page 15 Item: 5	Electrical	• Wire ends are outside of a Junction Box, which is a potential shock or electrocution hazard.
Garage	-	
Page 16 Item: 1	Roof Condition	 Shingles appeared weathered and with advance granular loss. See roof notes.
Kitchen	-	
Page 25 Item: 10	Sinks	• Suggest caulking along the edge of the sink. Water was leaking when testing the sink.
Bedrooms		
Page 29 Item: 10	Window Condition	• One of the windows in bedroom #2 comes off the track, recommend repairing for the safety and comfort of occupants.
Bathrooms		
Page 32 Item: 14	Plumbing	 Master bathroom plumbing is exposed under sink. Polybutylene plumbing observed, no deficiencies found with plumbing but should be noted.
Page 33 Item: 17	Shower Walls	• Suggest all tile edges and tub/shower walls be caulked and sealed to prevent moisture penetration additional mositure damage. All missing/damaged grouting should be replaced. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection, however moisture was found when tested behind loose tile.
Laundry		
Page 35 Item: 5	Dryer Vent	• Dryer vent pipe is disconnected and allowing link to land in the attic. This is a potential fire hazard as lint can catch a spark and coming into contact with insulation can ignite. Repair exhaust pipe.

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair. For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Inspection Details

1. Attendance	
	In Attendance: Client present • Buyer Agent present • Selling Agent present
2. Home Type	
	Home Type: Single Family Home
3. Occupancy	
	Occupancy: Vacant - Furnished • Access to some items such as: electrical outlets/receptacles, windows, wall/floor surfaces, and cabinet interiors may be restricted by furniture or personal belongings. Any such items are excluded from this inspection report.
4. Utilities Source	
	Materials: Electric Power • City Water • Well Water Materials: All utilities were on at time of inspection.
5. Garage Type	
	Materials: • Attached 2-Car Garage.
	Construction
1. Construction Obse	rvation
Good Margin Poor Not Not al Presen Inspect t ed	Materials: • Wood frame. Observations: • The construction of the home was structurally sound at the time of the inspection.
	Foundation
1. Slab Foundation	
Good Margin Poor Not Not al Presen Inspect t ed	Observations: • Concrete slab not visible due to floor coverings.
	Page 3 of 42

Grounds
1. Grading
Good Margin Poor Not Not Observations:
✓ I we will be wil
2. Driveway and Walkway Condition
Good Margin Poor Note Image: Poor Presen Image: Poor Note Image: Poor Image: Poor Note Observations: Image: Poor Image: Poor Presen Image: Poor Image: Poor Image: Poor Poor Poor Poor Image: Poor Image: Poor Poor Poor Poor Poor Image: Poor Image: Poor
3. Vegetation Observations
Good Margin Poor Presen Inspect Cood Margin Poor Not Inspect Cood Margin Poor Not Inspect Cood Margin Poor Not Inspect Cood Margin Poor Presen Inspect Cood Margin Poor Poor Poor Poor Poor Poor Poor Poo
4. Grounds Electrical
Good Margin Poor Not Not Inspect t ed ✓ No major system safety or function concerns noted at time of inspection.
5. GFCI
Good Margin Poor Not Not al Presen inspect t ed Some of the exterior outlets had no Ground Fault Circuit Interrupter (GFCI) protection of home electrical outlets was provided in the home at the time of inspection. Although GFCI protection may not have been required at the time the home was built, for safety reasons, consider upgrading the electrical system to include GFCI protection at the following locations: Bathrooms, Outside, Garages, Kitchens, Laundry rooms and Within 6 feet of all plumbing fixtures
Page 4 of 42



6. Plumbing

Good	Margin	Poor	Not	Not	
	aĭ		Presen	Inspect	Materials: PVC piping noted. • Polybutylene
			t	ėd	indicidade i vo pipilig notodi i vojskutjično

- Observations:
 - See notes in plumbing.

7. Exterior Faucet Condition



 $\frac{Not}{t}$ $\frac{Not}{ed}$ Location: East side of house. • South side of house. Observations:

Appears Functional.
Hose bib handle is coming off of structure. Recommend securing to prevent moisture intrusion into home and also damage to pipe.



8. Patio Location

Presen Inspect t ed Observations: Good Margin al Poor




• Patio is located in rear of home and Porch in front of home.



9. Patio Enclosure

Good Margin Poor Not No al Presen Insp



Not end inspect of the trees from the pool area are becoming too large for the this area. Recommend trimming down these trees to prevent damage to screens.





10. Patio and Porch Condition

Good	Margin al	Poor	Not Presen t	Not Inspect ed	ſ
1	~				•

Materials: Aluminum standing seam roof present. • Asphalt shingles noted.

• No major system safety or function concerns noted at time of inspection. Patio has both metal standing and asphalt shingle roof covering this area. Recommend sealing the seams above the patio roof and monitoring the shingles as they are showing early signs of deterioration.




Porch Roof

Porch Roof



Patio Roof




Pool
1. Air Booster Pump
Good Margin Poor Not Not al Presen Inspect
2. Deck Condition
Good Margin Poor Not Not Observations:
• Appears in satisfactory and functional condition with normal wear for its
3. Gate & Fence Condition
Good Margin Poor Not Not Inspect Materials: See grounds page.
Recommend 4 foot fence or better.
4. Filter
Good Margin Poor Not Not Inspect Observations:
• Diatom earth filter noted.
5. Skimmer and Basket
Good Margin Poor Not Not Inspect Observations:
✓ Functional.
6. Pool Heater Condition
Good Margin Poor Not Not Not al Presen Inspect t ed


1234 Main St, Orlando, FL



7. Lights




8. Pressure Gauge






9. Pumps









10. Jets



11. Structure Condition
Good Margin Poor Not Not Inspect Type: below ground
Materials: gunite Observations:
Limited Inspection Only
12. Tile
Good Margin Poor Not Not
al Presen Inspect t ed
13. Timer
Good Margin Poor Not Not Inspect Observations:
• present
14. Water Condition
15. Water Fill Unit Good Margin Poor Not Not Character for the State Sta
al Presen Inspect Observations:
• operated
16. Electrical
Good Margin Poor Not Not Observations:
 Some outlets were not accessible due to furniture and or stored personal items in the wat.
17. Hot Tub
Good Margin Poor Not Not al Presen Inspect





Roof

1. Roof Type

Materials:

• The main roof was a gable.

2 Roof Condition

2.1		2011	antion		
Good	Margin al	Poor	Not Presen t	Not Inspect ed	Materials: Inspected on roof.
					Materials: Asphalt shingles noted.
	✓				Observations:
	•				 No permit information available online. Roof appears to be original from when home was built. Some sections have been replaced but not completely. At the time of the inspection, asphalt composition shingles covering the roof
					f this have a made to be seen the and of their working lives. The large start

oof of this home appeared to be near the end of their useful lives. The Inspector recommends that before the expiration of your Inspection Objection Deadline, you consult with a qualified roofing contractor to discuss options and costs for replacement.



Second Level

3. Flashing

Presen Inspect t ed Observations: Good Margin Poor al






• The inspector observed no deficiencies when inspecting kick-out flashing.





Good Margin Not Not Presen Inspect t ed Poor Observations:





• The gutters had moderate general corrosion visible. Continued corrosion will eventually result in leaking gutters. Good maintenance practices will help extend the long-term service life of the gutters.














8. Fire Door	
Good Margin Poor Not Not Observations:	
• Appeared satisfactory and functional, at time of inspection.	
9. Garage Door Condition	
Good Margin Poor Not Not Not Inspect Materials: Roll-up door noted.	
No deficiencies observed.	
10. Garage Door Parts	
Good Margin Poor Not Not Inspect Observations:	
• The garage door appeared functional during the inspection.	
11. Garage Opener Status	
✓ Chain drive opener noted.	
12. Garage Door's Reverse Status	
Good Margin Poor Not Not Observations:	
Garage vehicle door auto-reverse is operable.	
13. Ventilation	
Good Margin Poor Not Not Observations:	
· Under eave soffit inlet vents noted.	
	Page 18 of 42




1234 Main St, Orlando, FL





5. Ceiling Fans






Dinning Room

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.




Family Room
1. Ceiling Condition
Good Margin Poor Not Not Presen Inspect t ed Materials: There are drywall ceilings noted.
2. Wall Condition
Good Margin Poor Not Not Inspect Inspect Materials: Drywall walls noted. • Painted finish noted.
3. Floor ^{Good} Margin Poor Not Inspect al Presen Inspect t ed • Laminate wood flooring.
4. Ceiling Fans
Good Margin Poor Not Inspect Observations: t ed ◆ Operated normally when tested, at time of inspection. Remote controlled.
5. Doors Good Margin Poor Not Not Observations:
✓ Double door entryway.


1234 Main St, Orlando, FL

6. Electrical
Good Margin Poor Not Not Not Not Not Observations:
7. Patio Doors
Good Margin Poor Not Not Not Not Not Not ed t ed ✓
8. Window Condition
Good Margin Poor Not Presen Inspect ed t ed Materials: Aluminum framed single hung window noted.
9. Fireplace
Good Margin Poor Not Not Not Inspect ed Materials: Free standing style wood burning stove noted.
Page 23 of 42

Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances. Kitchen appliances are only tested for basic functionality. If a more thorough review of appliances is needed, contact a licensed technician.





14. Window Condition
Good Margin Poor Not Not al Presen Inspect Materials: Aluminum framed single hung window noted.
 ✓ Observations: • One or more windows did not lock/latch properly, recommend repairs for
enhanced security/safety to occupants.
15. Plumbing
Good Margin Poor Not Not al Presen Inspect Observations:
• Limited review due to personal property stored in undersink cabinet.
16. Electrical
Good Margin Poor Not Not Observations:
 ✓ ✓ ✓ ✓
17. GFCI
Good Margin Poor Not Not Inspect Observations:
Good Margin Poor Not Not Observations:
Good Margin Poor Not Not Inspect Observations:
Good Margin Poor Not Not Not t t ed ◆ GFCI in place and operational.
Good Margin Poor Not Not Inspect Observations:
Good Margin Poor Not Inspect Observations: Image: Head of the second
Good Margin Poor Not the present inspect Observations: Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational. Image: the ded • GFCI in place and operational.
Good Margin Poor Not Inspect Observations: Image: Image
Good Margin Poor Present Inspect Observations: Image: I
Good Margin Poor Net Inspect Observations: Image: Presen Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Image: Poor Net Inspect • GFCI in place and operational. Good Margin Poor Net Inspect • Materials: There are drywall ceilings noted.
Good Margin Poor Net Inset Observations: Image: Poor Present Inset • GFCI in place and operational. Image: Poor Poor Poor Poor Poor Poor Poor Poo
Good Margin Poor Net Inset Observations: Image: Poor Present Inset • GFCI in place and operational. Image: Poor Poor Poor Poor Poor Poor Poor Poo
Good Margin Poor Net Inset Observations: Image: Poor Present Inset • GFCI in place and operational. Image: Poor Poor Poor Poor Poor Poor Poor Poo

3. Wall Condition



Not resen Inspect t d Decenvertione: Materials: Drywall walls noted. • Painted finish noted.

Observations:

 Patch observed in bedroom #4, storage observed in bedroom #2. Most areas were not accessible due to stored personal items. Areas that were visible appeared in serviceable conditions.







Bedroom #2

Bedroom #4

Bedroom #2



Master Bedroom

4. Floor Condition

Good Margin Not Not Presen Inspect t ed Poo Flooring Types: Hardwood flooring is noted.

Observations:



• The floor in this bedroom appeared to be in serviceable condition at the time of the inspection.



Bedroom #4



Bedroom #3



Bedroom #2



Master Bedroom

5. Ceiling Fans

Good Margin Poor Not Not Inspect t dd Observations:


• Operated normally when tested, at time of inspection.



Bedroom #4



Bedroom #3




Bedroom #2



Master Bedroom

6. Closets

Good Margin Poor Not Not Inspect



• The closet is in serviceable condition. Limited review due to stored personal items. Areas that were visible appeared in serviceable conditions.

1234 Main St, Orlando, FL


Bedroom #4	Bedroom #3	Bedroom #2
7. Doors Good Margin Poor Not Presen Inspect t ed Observations • Hollow woo		
8. Electrical Good Margin Poor Not Inspect t ed Observations The majorit Correctly.	s: ty of grounded receptacles were	e tested and found to be wired
9. Smoke Detectors Good Margin Poor Not Inspect al Poor Presen Inspect ed • The smoke	s: e detectors operated during the i	inspection.
✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓		nd budgeting for replacement for off the track, recommend
Bedroom #4	Bedroom #2	With the sector of the secto

Bathrooms

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring ... 1. Locations Locations: Master Bathroom • Half bathroom • Upstairs Bathroom 2. Ceiling Condition Not Presen Inspect t Observations: There are drywall ceilings noted. Good Margin Poor Observations: Ceilings in the bathrooms appeared in serviceable conditions. 3. Floor Condition $\underset{t}{\overset{Not}{\underset{ed}{\mathsf{Presen Inspect}}}} \overset{Not}{\underset{ed}{\mathsf{Materials: Ceramic tile is noted}}}.$ Good Margin Poor **Upstairs Bathroom** Master Bathroom 4. Walls Not Not Presen Inspect t ed Good Margin Poor **Observations:** Drywall painted finish. Damage observed to the wall, repair as needed. 5. Cabinets Good Margin al Not Not Presen Inspect t ed Poor **Observations:** No deficiencies observed. 6. Counters Good Margin Poor Presen Inspect t ed Observations: Solid Surface tops noted. Upstairs Bathroom

Page 30 of 42

7 Doors	
7. Doors Good Margin Poor Not Not al Presen Inspect	Observations:
t ed	Hollow wood doors.
	Pocket door does not latch or lock at half and master bathrooms.
Half	Bathroom Master Bathroom
8. Electrical	Observations: • No major system safety or function concerns noted at time of inspection.
9. GFCI	
Good Margin Poor Not Not al Presen Inspect t ed	Observations:
	GFCI in place and operational
10. Exhaust Fan	
Good Margin Poor Not Not al Presen Inspect ed	Observations: • The bath fan was operated and no issues were found.
11. Toilets	
Good Margin Poor Not Not al Presen Inspect ed	Observations: • Observed as functional and in good visual condition.
12. Venting	
Good Margin Poor Not Not al Presen Inspect ed	Observations: • This bathroom had an operable source of ventilation at the time of the inspection.
13. Mirrors	
Good Margin Poor Not Not al Presen Inspect	Observations:
✓	Mirror appeared in serviceable conditions at time of inspection.
14. Plumbing	
Good Margin Poor Not Not al Presen Inspect ed	Observations: • Master bathroom plumbing is exposed under sink. Polybutylene plumbing observed, no deficiencies found with plumbing but should be noted.
	Page 31 of 42





Master Bathroom

17. Shower Walls

Good Margin Poor Not Not Inspect Observations:

Ceramic tile noted.
Suggest all tile edges and tub/shower walls be caulked and sealed to prevent moisture penetration additional mositure damage. All missing/damaged grouting should be replaced. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection, however moisture was found when tested behind loose tile.



Upstairs Bathroom




Upstairs Bathroom




Upstairs Bathroom




Master Bathroom







4. Plumbing






5. Dryer Vent


•


Good Margin Poor Not Inspect

• Dryer vent pipe is disconnected and allowing link to land in the attic. This is a potential fire hazard as lint can catch a spark and coming into contact with insulation can ignite. Repair exhaust pipe.










7. Filters
Good Margin Poor Presen Inspect Location: Located in a filter grill in an interior area wall.
Observations:
✓ MAINTENANCE: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. Remember that dirty filters are the most
common cause of inadequate heating or cooling performance.
8. Thermostats
Good Margin Poor Not Not al Presen Inspect Observations:
f = f =
✓ • Functional at the time of inspection.
• Thermostats are not checked for calibration or timed functions.
Plumbing/Water Heater
1. Main Water Shutoff
Good Margin Poor Not Not al Presen Inspect Materials:
• Left side of home
 ✓ Observations: • No deficiencies noted
2. Water Line Material
Good Margin Poor Not Not Inspect Materials: Polybutylene • Plastic
Observations:
• The water supply pipes are Polybutylene plastic (PB). This system of
plumbing has experienced a higher than normal failure rate associated with leaks where the pipes are joined together. There is also a current theory that
chemicals in municipal water systems react with the piping and resins in the
fittings, weakening the pipes and joints. The manufacturers have been
involved with and settled class action lawsuits alleging manufacturing defects with this plumbing system containing plastic or metal insert fittings (including
copper and brass). Recommend you research further this type of plumbing
system and rely on the evaluation and advice of a licensed plumbing
contractor prior to the close of escrow.No deficiencies observed at the visible portions of the supply piping.
3. Water Heater Condition
Good Margin Poor Not Not Inspect Heater Type: Electric
✓ Location: The heater is located in the garage.
• No major system safety or function concerns noted at time of inspection.



4. Base




5. TPRV

Good Margin Poor Not Not Inspect Observations:



6. Number Of Gallons







7. Overflow Condition




• Appears to be in satisfactory condition -- no concerns.











Not Presen Inspect ed Tile Good Margin Poor al



4. Damper





5. Flue Pipe

 \checkmark

Good Margin Poor al

